



Firmware for PT-G503 Series Release Notes

Version: v5.2	Build: N/A
Release Date: Aug 02, 2022	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added the Nodes Table, which displays supervision frame information.
- Added support for RSTP Grouping in HSR mode.
- Users can now customize the IED name in the MMS feature.

Enhancements

- Added for support for TLS 1.2.

Bugs Fixed

N/A

Changes

N/A

Notes

N/A



Version: v5.1	Build: N/A
Release Date: Apr 13, 2022	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- The PTP boundary clock Best Master Clock algorithm behaves abnormally.
- The P2P path delay correction field does not update correctly.
- The SNMP polling function for MXview always fails.
- Forcing the port speed to 100M/10M in the Web UI does not work.

Changes

N/A

Notes

N/A



Version: v5.0	Build: Build_18071716
Release Date: Dec 09, 2019	

Applicable Products

PT-G503 Series

Supported Operating Systems

N/A

New Features

- The flash memory had been replaced.

Enhancements

N/A

Bugs Fixed

- The PT-G503 Series could not upload firmware using the ABC-02 Series.

Changes

N/A

Notes

Product versions V1.0.2 and prior are compatible with all firmware versions. Product versions V2.0.0 and later are compatible with firmware V5.0 and later.



Version: v4.3	Build: Build_17090110
Release Date: Oct 18, 2017	

Applicable Products

PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- PTP: Supports BC/TC P2P/E2E.
- PTP: Supports Power profile.
- PTP: Supports 2-step to 1-step.
- IEC 62439-3: Configurable supervision frame.
- Security: Added a warning message for when the default password has not changed yet.
- Security: Encrypts security keys in the user interface.

Bugs Fixed

- Cross-site scripting vulnerability.
- Denial of Service attack vulnerability.
- Privilege escalation vulnerability.
- SSL v2/v3 vulnerability in HTTPS.
- Web console cannot be accessed when the SNMP get bulk service is running.
- Specific CLI command caused the switch to reboot with default settings.
- PTP timestamp error in announce Message.
- System rebooted after specific CLI commands.
- Telnet hangs when SSH is disabled.
- For PT-G503 models that use SFP-1G Series cannot link up with EDR-G903 models.

Changes

- Renamed RSTP transparent to RSTP Grouping.

Notes

N/A



Version: v4.2	Build: Build_17022316
Release Date: N/A	

Applicable Products

PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A



Version: v4.1	Build: N/A
Release Date: N/A	

Applicable Products

PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV

Supported Operating Systems

N/A

New Features

- First release for PT-G503 Series.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A