



## Firmware for NPort IA5150A/IA5250A Series Release Notes

<b>Version: v1.3</b>	<b>Build: Build 16100514</b>
<b>Release Date: Nov 10, 2016</b>	

### Applicable Products

NPort IA5150A, NPort IA5150AI, NPort IA5150AI-T, NPort IA5150A-T, NPort IA5250A, NPort IA5250AI, NPort IA5250AI-T, NPort IA5250A-T, NPort IA5150A-IEX, NPort IA5150AI-IEX, NPort IA5150AI-T-IEX, NPort IA5150A-T-IEX, NPort IA5250A-IEX, NPort IA5250AI-IEX, NPort IA5250AI-T-IEX, NPort IA5250A-T-IEX

### Supported Operating Systems

N/A

### New Features

N/A

### Enhancements

- Enhanced web login security and supports 5 users logged in simultaneously.
- Extended HTTP challenge ID length from 32 bits to 256 bits.
- Enabled the default password "moxa".
- Increased CSRF protection mechanism.
- Increased XSS protection mechanism.
- The IP address of the NPort can be set to an address ending with 0 or 255.
- Supports "ARP probe" in RFC5227. NPort would respond for ARP requests with sender IP address 0.0.0.0.

### Bugs Fixed

- NPort cannot send email using Google's SMTP server.
- In pair connection mode, master does not pull down RTS/DTR signal after the TCP connection is broken.
- Command port sends lots of "D\_ASPP\_CMD\_ALIVE" packets after running for 50 days.
- NPort may reboot or hang from several buffer overflow attacks through Telnet, SSH, DSCI, SNMP, HTTP, and HTTPS.

### Changes

N/A

### Notes

N/A



<b>Version: v1.2</b>	<b>Build: Build 15041515</b>
<b>Release Date: N/A</b>	

### **Applicable Products**

NPort IA5150A, NPort IA5150AI, NPort IA5150AI-T, NPort IA5150A-T, NPort IA5250A, NPort IA5250AI, NPort IA5250AI-T, NPort IA5250A-T, NPort IA5150A-IEX, NPort IA5150AI-IEX, NPort IA5150AI-T-IEX, NPort IA5150A-T-IEX, NPort IA5250A-IEX, NPort IA5250AI-IEX, NPort IA5250AI-T-IEX, NPort IA5250A-T-IEX

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Uses model name instead of "NULL" for SNMP object "sysDescr".
- Supports connecting to the server by domain name and the server IP will change dynamically.
- Supports updating the ARP table by gratuitous ARP.
- Supports time synchronization with an NTPv4 server.
- Supports RFC2217 NOTIFY-LINESTATE for Transfer Shift Register Empty and Transfer Holding Register Empty.

### **Bugs Fixed**

- If an SNMP GETNEXT command is issued on an object that does not exist, 'no such name error' is displayed.
- When DHCP renews IPs, if the IP was originally given by a relay agent, NPort should send a DHCP request to the relay agent, not the DHCP server.
- In Real COM mode, when the modem status of the NPort's serial port is changed frequently, the NPort will sometimes fail to notify the change to the driver.
- In reverse telnet mode, the NPort will try to subnegotiate the COM port control options without option negotiation first.
- In RFC2217 Mode, if the Ethernet data has many FF characters, some data may be lost while passing the data to the serial side.
- Modified parsing data mechanism to fix import file failure.
- Unable to see the baud rate through a Telnet console on the "View settings" side.
- System reboots when receiving IGMP packets.
- The trap settings for port auto warning in the configuration file will be set to email settings after import.
- When both serial ports are set to TCP server mode, the connection on port 1 works normally, but will fail after a connection on port 2 is established.

### **Changes**

N/A

### **Notes**

N/A