



## Firmware for UC-5100 Series Release Notes

<b>Version: v1.2</b>	<b>Build: Build 19070818</b>
<b>Release Date: Jul 08, 2019</b>	

### Applicable Products

UC-5101-LX, UC-5102-LX, UC-5111-LX, UC-5112-LX, UC-5101-T-LX, UC-5102-T-LX, UC-5111-T-LX, UC-5112-T-LX

### Supported Operating Systems

Moxa Industrial Linux (Debian 9)

### New Features

- Includes the mx-ver utility.
- Includes the mx-module-ctl utility, which replaces the mx-mod-ctl utility.
- Includes can-utils and bridge-utils packages.

### Enhancements

- Upgrades kernel version to CIP Linux 4.4.154.
- Upgrades the TPM v2.0 driver.
- Includes security patches: CVE-2018-9363, CVE-2018-10882, CVE-2018-10881, CVE-2018-10877, CVE-2018-10876, CVE-2018-10883, CVE-2018-10853, CVE-2018-6412, CVE-2018-1093, CVE-2018-1092, CVE-2017-8824, CVE-2018-1000004, CVE-2017-8824, CVE-2017-5715, CVE-2017-1000410, CVE-2017-5753, CVE 2017-5715, CVE-2017-17741, CVE-2017-1000407, CVE-2017-0861, CVE-2017-7518, CVE-2017-13080, CVE-2017-12193, CVE-2017-15265, CVE-2017-0786, CVE-2017-12154, CVE-2017-1000252, CVE-2017-12153, CVE-2017-11600, CVE-2017-10663, CVE-2015-8944, CVE-2016-6213, CVE-2017-1000370, CVE-2017-1000371.

### Bugs Fixed

- Modified the platform initialization script to fix an issue in an mx-uart-ctl utility option.
- Unload the WLAN module before powering off the SparkLAN WPEQ-160ACN module.

### Changes

- Removes the auto mount SD and auto mount USB features.
- Removes the mx-firm-upgrade, mx-firm-downgrade, and mx-overlay commands.

### Notes

N/A



<b>Version: v1.1</b>	<b>Build: N/A</b>
<b>Release Date: Apr 19, 2019</b>	

### **Applicable Products**

UC-5101-LX, UC-5101-T-LX, UC-5102-LX, UC-5102-T-LX, UC-5111-LX, UC-5111-T-LX, UC-5112-LX, UC-5112-T-LX

### **Supported Operating Systems**

Moxa Industrial Linux (Debian 9)

### **New Features**

- First release.

### **Enhancements**

N/A

### **Bugs Fixed**

N/A

### **Changes**

N/A

### **Notes**

N/A