



Software Release Note

Software Name: VPort 364A Series

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
V1.5	Build 16032410	N/A	VPort364A VPort364A-T	N/A	1. The sequence of system log is changed to list the older in the top. 3. The maximum position (400, 300) of OSD is changed to the middle of image.	N/A	1. Fix the issue that the telnet cannot be disabled. 2. Fix the issue that the multicast connection cannot be up to 30. 3. Fix the issue that the firmware upgrade cannot be executed in chrome and firefox.	N/A
V1.3	N/A	N/A	VPort364A VPort364A-T	IndigoVision support	N/A	N/A	N/A	N/A
V1.2	N/A	N/A	VPort364A VPort364A-T	Genetec support	N/A	N/A	N/A	N/A
V1.1	N/A	N/A	VPort364A VPort364A-T	N/A	N/A	N/A	N/A	ONVIF update
V1.0	N/A	N/A	VPort364A VPort364A-T	Newly released	N/A	N/A	N/A	N/A